



Est 1990


# 0-180° fittings

Fitting at an angle of up to 180°. The fitting is used where the machine guard needs to be set up at angles other than 90°.



## Models

### ARTICLES / DESCRIPTION



**T01-01**  
Fittings for creating corners up to 180°